

### - Site Report -

Date: September 26, 2012

IRD Sales Order: To: Dawn Patton From: Bryan Knight

Project Name/Location: LTPP Buckeye AZ I-10 E mp 109

Service Date(s): June 23 2010

**Job Description: Maintenance Visit** 

### **Work Completed:**

Recorded electrical readings of all in road sensors and Solar Panel output OK.

• Logged onto WCU and monitored sensor performace OK.

Performed visual inspection of road surface for inroad sensors OK.

• Performed general housekeeping of equipment cabinet and filter.

6/19/96 IRD FORM No.: 1304A




# INTERNATIONAL ROAD DYNAMICS INC.

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>





702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>





## ™TERNATIONAL ROAD DYNAMICS INC.

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>



Work Remaining: None

Work Kemaning. None
Schedule Include Estimate to Complete (on-track, ahead, behind):
Parts Used:
Pre-mature Equipment Failure:
Mileage / Travel Time: Total Travel: 2 hrs Total Onsite: 1 hr
Safety Concerns:
Issues Related to Sub-Contractors:
Other Notes:

### **Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		